

www.equipmentsearch.com/exports/ag/script.php?token=7910

Disable Cookies CSS Forms Images Information Miscellaneous Outline Resize Tools View Source Options

This XML file does not appear to have any style information associated with it. The document tree is shown below.

```
- <XML>
- <Equipment>
  <Equip_ID>13323654</Equip_ID>
  <Dealer_No>7910</Dealer_No>
  <StoreLocation>Lindsay</StoreLocation>
  <Stock_No>2390400</Stock_No>
  <Serial_No0/>
  <New>U</New>
  <year>0</year>
  <Make>BRDCO</Make>
  <Model>Bradco 2 Attachment</Model>
  <Amt_List>1550.00</Amt_List>
- <Notes>
  Set of 2 rear skidsteer stabilizers/outriggers Hydraulic cylinders protected on inside Includes mounting kit for New Holland L170 skidsteer AS NEW CONDI
  </Notes>
  <Type>ADATT</Type>
  <MisType>Attachments</MisType>
- <EqImage>
  <Image_No>1</Image_No>
  - <ImageUrl>
    http://www.equipmentsearch.com/uploadedimages/7910/13323654_6.jpg
  </ImageUrl>
  </EqImage>
- <EqImage>
```